### ADDENDUM NO. 1

DATE: July 13, 2018

Project: ROBBINS LIBRARY EXTERIOR ENVELOPE REPAIRS 700 MASSACHUSETTS AVENUE TOWN OF ARLINGTON, MASSACHUSETTS, BID NO. 18-16 CBI JOB NO.: 17152

In accordance with documents prepared by: CBI Consulting LLC (CBI)

#### TO: ALL PLANHOLDERS--BIDDERS--PROPOSERS--CONTRACTORS

This Addendum No. 1 forms part of and modifies the Construction Documents dated July 5, 2018. Acknowledge receipt of this Addendum in the space provided on the FORM FOR GENERAL BID. Failure to do so may subject the bidder to disqualification.

The attention of bidders submitting bids for the above subject project is called to the following addendum to the specifications and drawings. The items set forth herein, whether of omission, addition, substitution, or clarifications are all to be included in and form a part of the bid submitted.

This Addendum consists of ITEMS 1 - 2 which are hereby incorporated into the Bidding Documents:

#### **BIDDER QUESTIONS:**

#### ITEM NO. 1:


- 1.1 QUESTION...Does the successful bidder have to be DCAM certified in Historical Masonry? ANSWER...Yes. The successful bidder must be DCAM Certified in Historical Masonry.
- 1.2 QUESTION...To whom shall the Bid Bond be made out to? ANSWER...Town of Arlington, Massachusetts
- 1.3 QUESTION...Can the bid deadline be extended? ANSWER...As of now there is no intention to extend the Bid Date.
- 1.4 QUESTION...Please confirm that only the spandrel panel to frame gets new sealant. *ANSWER...Only the exiting gaskets between the aluminum spandrel panel and the metal is to be removed and disposed, and replaced with new silicone sealant.*

#### **REVISIONS TO DRAWINGS:**

#### ITEM NO. 2: ARCHITECURAL

- 2.1 DELETE: DRAWING A2-03 INSERT: DRAWING A2-03 Addendum No. 1 of 07/13/18 (ENCLOSED) SUMMARY: Revise Note Identification on Elevation Drawing for work at Spandrel Panels on the 1990's Building from 15 to 16.
- 2.2 DELETE: DRAWING A2-04 INSERT: DRAWING A2-04 Addendum No. 1 of 07/13/18 (ENCLOSED) SUMMARY: Revise Note Identification on Elevation Drawing for work at Spandrel Panels on the 1990's Building from 15 to 16.

#### FAILURE TO ACKNOWLEDGE THIS ADDENDUM ON YOUR BID FORMS MAY BE CAUSE FOR BID REJECTION.



# WEST EXTERIOR ELEVATION

## **REPAIR AND RESTORATION WORK NOTES:** 1. CUT AND POINT EXISTING SANDSTONE (1890'S BUILDING) FIELD STONE, WATER TABLE & ENTABLATURE MORTAR JOINTS INCLUDING HORIZONTIAL BED JOINTS AND VERTICAL HEAD JOINTS. APPLY NEW MORTAR WITH A BEADED "GRAPE VINE" PROFILE JOINT TO MATCH EXISTING. TOTAL QUANTITY OF 750 LINEAL FEET IN SELECT AND RANDOM ACROSS ALL ELEVATIONS AS SELECTED BY ARCHITECT. REFER TO UNIT PRICES – SPECIFICATION 01 22 00. 2. CUT AND POINT EXISTING SANDSTONE (1890'S BUILDING) WINDOW TRIM, MOULDING, COLUMN PILASTERS AND COLUMN CAPITOL MORTAR JOINTS INCLUDING HORIZONTAL BED JOINTS AND VERTICAL RUNNING. APPLY NEW MORTAR WITH A BEADED PROFILE JOINT TO MATCH EXISTING. TOTAL QUANTITY OF 200 LINEAL FEET IN SELECT AND RANDOM ACROSS ALL ELEVATIONS AS SELECTED BY ARCHITECT. REFER TO UNIT PRICES – SPECIFICATION 01 22 00. 3. CUT AND POINT EXISTING ORNATE SANDSTONE (1890'S BUILDING) CORNICE, SOFFIT, DENTILS, BRACKETS AND PEDIMENT MORTAR JOINT FEATURES INCLUDING HORIZONTIAL BED JOINTS AND VERTICAL JOINTS. APPLY NEW MORTAR WITH A BEADED PROFILE JOINT TO MATCH EXISTING. TOTAL QUANTITY OF 375 LINEAL FEET IN SELECT AND RANDOM LOCATIONS ACROSS ALL ELEVATIONS AS SELECTED BY ARCHITECT. REFER TO UNIT PRICES – SPECIFICATION 01 22 00. 4. ROUTE AND CLEAN EXISTING CRACKS IN ANY SANDSTONE (1890'S BUILDING) DETAIL OR ELEMENT, AND FILL CRACKS WITH INJECTION RESTORATION REPAIR MORTAR. TOTAL QUANTITY OF 50 LINEAL FEET IN SELECT AND RANDOM LOCATIONS ACROSS ALL ELEVATIONS AS SELECTED BY ARCHITECT. REFER TO UNIT PRICES – SPECIFICATION 01 22 00 AND DEDUCT ALTERNATE NO. 4. 5. REPLACE GLASS AT EXISTING HALF ROUND ALUMINUM STORM WINDOWS FOR <u>SIX (6) LOCATIONS</u> ON THE 1890'S LIBRARY BUILDING. REMOVE EXISTING ALUMINUM STOP AND SALVAGE FOR REINSTALLATION. REMOVE AND DISPOSE OF EXISTING GLASS, AND INSTALL NEW 1/4-INCH CLEAR TEMPERED SAFETY GLASS. REINSTALL ALUMINUM SET IN A BED OF NON-SAG SINGLE COMPONENT, SILICONE SEALANT. REFER TO UNIT PRICES – SPECIFICATION 01 22 00 6. REPLACE EXISTING SEALANT AND MORTAR JOINTS OF THE EXTERIOR GRANITE STONE STAIRS, WITH INTERMEDIATE CONCRETE LANDING AT MAIN ENTRANCE OF THE 1890'S LIBRARY BUILDING. CUT, REMOVE AND DISPOSE OF 100% ALL EXISTING VERTICAL AND HORIZONTAL JOINT SEALANTS, INCLUDING UNDERLYING MORTAR A MINIMUM OF 1-1/2-INCHES OR UNTIL SOUND MORTAR FROM ALL GRANITE STONE STAIR AND CONCRETE LANDING JOINTS. APPLY NEW POINTING MORTAR TO WITHIN 1/2-INCH OF THE SURFACE AND APPLY POLYURETHANE SEALANT TO ALL GRANITE STONE JOINTS AND CONCRETE LANDING JOINTS. STAIRS SHALL BE POWER WASHED CLEANED. REFER TO DEDUCT ALTERNATE NO. 5. 7. CUT AND POINT EXISTING ARCHITECTURAL CAST STONE (1930'S BUILDING) FIELD STONE MORTAR JOINTS INCLUDING HORIZONTIAL BED JOINTS AND VERTICAL HEAD JOINTS. APPLY NEW MORTAR WITH A BEADED PROFILE JOINT TO MATCH EXISTING. TOTAL QUANTITY OF 180 LINEAL FEET IN SELECT AND RANDOM LOCATIONS ACROSS ALL ELEVATIONS AS SELECTED BY ARCHITECT. REFER TO UNIT PRICES -SPECIFICATION 01 22 00.

