

Arlington Central School Senior Center / HHS Renovation

Progress Photo-documentation

2-2-21 PTBC Meeting



Rigging cooling tower on pad with truck crane



New cooling tower adjacent to north parking lot



Kitchen ceiling area that requires additional LVL reinforcement framing



Kitchen ceiling area that requires additional LVL reinforcement framing



East wall of Yoga room on GF. Old windows previously blocked in due to raising of exterior grade



Previous contractor failed to fully remove one window frame and sash before blocking in the opening and installing drywall on interior. Moisture infiltration evident. Mitigated by new work on east side.






Grease trap for 1st floor kitchen in Ground floor level crawl space



Mechanical room HV unit housekeeping pad extension



Mechanical room HV unit housekeeping pad extension



Deletion of north entry roof canopy