Summary

At the intersection of Churchill Ave, Endicott Rd, and Gloucester St we believe the road is excessively wide, which leads to unsafe pedestrian crossing, unsafe vehicle merging, and an unnecessary lack of green space. To give perspective, the current distance pedestrians cross is equivalent to 10-15 Subaru Forester SUVs side-to-side. We kindly ask the town to explore and act upon options for decreasing the area of paved space, increasing green space, and supporting safer crossing of pedestrians and drivers.

Areas for Intersection Improvement

The intersection of Churchill Ave, Endicott Rd, and Gloucester St is depicted in Figure 1 below with example images from a pedestrian point of view in Appendix 1. The wide road width entering the intersection, in addition to the size of the intersection itself, lead to multiple problems including:

<u>Pedestrian safety</u>: While the roads that feed into the intersection are about 30 feet wide, the primary pedestrian crossing areas range from 62 - 90 feet wide and do not have crosswalk signage. These large distances take extra time to cross on foot and do not have any protections from traffic. Of note, this intersection is heavily trafficked by high school students walking to/from school.

Vehicle safety: Vehicles coming from Gloucester or Endicott and turning onto Churchill have multiple challenges including (1) uncertainty where to stop given the wide road opening and (2) poor visibility looking south along Churchill given a hill and curve in the road. Furthermore, given the obtuse angle of the intersection, it's not always clear what is the main flow of traffic and subsequently vehicles tend to merge or turn at higher speeds than may be safe.

Green space: All the excess pavement area could instead be green space. Our impression is that Arlington recognizes the importance of green space, including water runoff buffering, reduction of urban heat islands, and general citizen enjoyment.




Figure 1: Google image of the intersection. Distances measured in feet and done by hand using a tape measure.

Potential Solution

We believe there are options for extending the curbs and/or adding islands to address some of the issues raised above. Below in Figure 2 is one option we roughly sketched as a potential solution to the problems raised. A similar approach was taken at the intersection of Gray St. And Endicott Rd with success in slowing traffic on Endicott. We ask the town to consider this option, as well as explore additional solutions, to significantly improve this intersection and the lives of people who use it.



Figure 2: Sketches of alternate intersection design

Thanks for your consideration in this matter. Please find signatures on the following page

Name	Address	Date	Signature
Devin and Brittany Bridgen	25 Endicott	1/1/2023	Deflace Age
Daviel Sheely	141 6va y 51	1/1/2013	Vamel Holy
Sns an Vik	141 Gray St	1/1/2023	Susan Vik
1. David Leslie	145 Gray/st	1/1/2003	fleten
Katarzyna Bryc	145 Gray St.	1/1/2023	120 Pu
Chis Chiappa	38 Temple	11/2023	Class
Maggie Benthall	42 Temple St,	1/1/2023	MR Benthall
having any	of Endeding	1(1/2)	Jan my
Jean Yodopt	70 Chrohill Are	1-1-23	E Pa Var
Ricardhi Grandon	8 Endico14 Rd	1/1/20	3
Shery/Ch She	67 Churchill he	1/8/2013	Theu Reiser
DAVID APTAMER	67 CAUNCHIN AN	1/8/2023	Jun Ste
ALCE TSAL-MARIE		1/7/2023	0/1/2
RENE SINARD	34 Temple St	1/7/2023	
Mary Perry	27 Tempte St	1126/23	Mary Perry
Sessica Nordgren	19 Sovenst.	1/26/27	
Cynthic English	54 Temple IT	1 28 23	
Jean-Charles Marie	35 Temple St	02/05/23	Maria
,			



Looking north from the intersection of Endicott and Gloucester



Looking south-east from the intersection of Endicott and Gloucester