Arlington Central School Senior Center / HHS Renovation

Progress Photo-documentation

1-19-21 PTBC Meeting





New switchgear panel



New switchgear panel





Panoramic view of switchgear panels, electric panels and boilers.














Reuse of existing door and frame in new framed wall of 1st floor. New framing required vertical shim due to throat width of door frame.




New wall framing on 1st floor



Utility installation at ceiling in multipurpose room on 1st floor.



HV units in Basement mechanical room



Abandoned steam radiator obstruction in Chimney B flue



Precast stone sample with mis-matched fluting.



North entry with shallow gas line and gutter downspout drain piping conflicts




North entry with shallow gas line and gutter downspout drain piping conflicts



Existing gas service piping shallow depth and with 2 repair couplings



NGrid Gas prefabricating new gas service line for north entry



NGrid Gas installing new gas service and piping



New gas meter