

Transportation Advisory Committee
Fisher and Fayette
27 September 2005

Report: Request for Stop Signs at Fisher/Fayette

Background

Memo from Oakes Plimpton to Board of Selectmen stating: “**Stop signs lacking at the intersections of Fisher and Fayette (or is it Bellington).**” TAC tasked to review need for stop signs.

Analysis

- Intersection is a 90 degree four way intersection
- Intersection currently uncontrolled
- Very low volume roads
- Good sight lines on 3 of 4 approaches
- Sidewalks clearly visible on all 4 corners
- Nature of surrounding area and relative shortness of roads appears to keep speeds low.
- No accident history
- Primarily local traffic – no major cut through pattern identified

Conclusion

- Intersection does not have significant safety or capacity problems as it currently functions (uncontrolled)

Recommendation

Transportation Advisory Committee recommends that no action be taken regarding the installation of stop signs at the intersection of Fisher and Fayette.

Respectfully submitted: Joe Cahill, 27 September 2005