

# **Arlington Central School Senior Center / HHS Renovation**

**Progress Photo-documentation**

**12-15-20 PTBC Meeting**



Installation of Z-Liner for exhaust using chimney flue.



Installation of drainage at east elevation



**Backfill / grading at East elevation**



Pouring new concrete pad at east entry



Roofers installing EPDM lining in 1984 gutter system



Demolition of Ground Floor at east conference room



Demolition of Ground Floor at former Retirement Office



**Demolition of Ground Floor at former Retirement Office**



Opening of Ground Floor plywood on raised floor



Demolition at Ground Floor



Demolition at former HSS office area



Demolition at former HSS office area



Existing ductwork under Ground Floor raised floor



Ceiling patch, new ductwork, and soffit framing in Multi-Purpose Room



Ceiling patch, new ductwork, and soffit framing in Multi-Purpose Room




Panoramic view of work in Multi-Purpose Room facing west



Panoramic view of work in Multi-Purpose Room facing north from center of room



Boiler room raised floor with new switchgear conduit in revised location



**Raised floor joist with existing check and cutout requiring repair.**



Occupied HSS Reception and office area



Occupied HSS office area



Occupied HSS Reception area