

Arlington Central School Senior Center / HHS Renovation

Progress Photo-documentation

12-7-21 PTBC Meeting



Shoring and demolition of the brick wall at the south entry



Shoring and demolition of the brick wall at the south entry



Shoring beams as viewed from the Main Hall.



Preparing the wall opening for new structural steel beams



Installation of precast stone stairs



Installation of precast stone stairs



Installation of precast stone stairs



Stove and appliances installed under the kitchen hood



Dishwasher and sink in kitchen



Installation of kitchen serving line and associated food service equipment



Installation of linoleum tile in Art Room