

Arlington Central School Senior Center / HHS Renovation

Progress Photo-documentation

2-1-22 PTBC Meeting



View of Pool Room



View of Game Room from Pool Room



COA reception carpet



View of Kitchen



View of Kitchen back room with mop sink cabinet, ice maker and refrigerator



Kitchen mop sink cabinet



Charging station installation in Cafe



Oak railing delivered for Main Hall wall openings at Stairs #3



Whiteboards at Exercise Room




Room signage



Countertop installed by Town in Drop-in Room



New railings at west entry



Stainless steel canopy bracket for support rods



View of south entry canopy



Pouring concrete overlay in south entry vestibule



Concrete pour at south entry