Arlington Central School Senior Center / HHS Renovation

Progress Photo-documentation

2-15-22 PTBC Meeting





Maple Street entrance doors



Maple Street entrance canopy framing with spray foam insulation at beams



Maple Street entrance canopy sheetmetal edge mockup




Maple Street entrance canopy EPDM roof



Library with furniture




Library with furniture




COA office reception



COA Directors office








Cafe with furniture




Cafe with furniture




Exercise room retained by KSR as a shop area



Pool tables in Pool Room




Drop-in Room on 1st floor



Drop-in Room on 1st floor



Supergraphics for wayfinding in GF corridor



Supergraphics for wayfinding in GF corridor



Supergraphics for wayfinding in GF corridor