





Photo #1 – Building B MEP in Progress (10/10/23)



Photo #2 – Building B MEP in Progress (10/10/23)



Photo #3 – Building D Exterior Flashing/Repointing in Progress (10/10/23)



Photo #4 – Sitework in Progress (10/10/23)



Photo #5 – Building E Roof and Wall Panels Complete (10/10/23)



Photo #6 – Building E Roof and Wall Panels Complete (10/10/23)



Photo #7 – Building D Lintel Replacement (10/17/23)




Photo #8 – Building D Lintel Replacement (10/17/23)